## 

## INDEX TO PHOTOGRAPHS

North (main) and west elevations, looking east

Chicago, Burlington and Quincy Railroad, West Iowa Division-Creston Station (Creston Municipal Complex) 116 West Adams
Creston
Union County
Iowa

HABS No. IA-150

Ted Wall, photographer, summer 1981

IA-150-1

IA-150-23

/	-,,-, (,,,,,,
IA-150-2	North and east elevations, looking west
IA-150-3	East and south elevations
IA-150-4	South and west (partial) elevations
IA-150-5	Door, south elevation
IA-150-6	West and south (partial) elevations
IA-150-7	Interior, waiting room, horizontal view
IA-150-8	Interior, waiting room, vertical view
IA-150-9	Interior, council chamber, 2nd floor
) IA-150-10	Photocopy, elevation and site plan
IA-150-11	Photocopy, plan
ÍA-150-12	Photocopy, section through general waiting room
IA≍150-13	Photocopy, detail of canopy and cellar window
IA=150-14	Photocopy, exterior double doors
IA-150-15	Photocopy, 2nd story window and cornice
IA-150-16	Photocopy, detail of door between general waiting room and hall
IA-150-17	Photocopy, detail of door in woman's waiting room
IA-150-18	Photocopy, waiting room details
IA-150-19	Photocopy, roof truss
IA-150-20	Photocopy, general drawing, roof truss
IA-150-21	Photocopy, diagram of framing for fireproofing attic
IA-150-22	Photocopy, detail of roof truss "A"

Photocopy, detail of roof truss "B"